

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 05/31/11</p> <p>Facility Number: 002280 Provider Number: 155723 AIM Number: NA</p> <p>Surveyor: Lex Brashear, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, River Pointe Health Campus was found not in compliance with Requirements for Participation in Medicare, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This two story facility was determined to be of Type V (111) construction and was fully</p>			K0000	<p>The submission of this plan of correction does not indicate an admission by River Pointe Health Campus that the findings and allegations herein are an accurate and true representation of the quality of care and services provided to the residents of River Pointe Health Campus. This facility recognizes it's obligation to provide legally and medically necessary care and services to its residents in an economic and efficient manner. The facility hereby maintains it is in substantial compliance with the requirements of participation for comprehensive health care facilities. To this end, this plan of correction shall serve as the credible allegation of compliance with all state and federal requirements governing the management of this facility. It is thus submitted as a matter of statute only. We are also requesting paper compliance for the follow up on this plan of correction.</p>		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0029 SS=E	<p>sprinklered. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors, and resident rooms. The facility has a capacity of 60 and had a census of 56 at the time of this survey.</p> <p>Quality Review by Robert Booher, REHS, Life Safety Code Specialist-Medical Surveyor on 06/06/11.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p> <p>One hour fire rated construction (with ¾ hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1</p> <p>Based on observation and interview, the facility failed to ensure 1 of 8 hazardous area room doors, such as a room over 50 square feet containing a large amount of combustible material,</p>			K0029	K 0029No residents suffered any ill effects from the deficient practice. There were 16 residents that had the potential to be affected by the deficient practice.A self closing door was installed on the maintenance door.		06/16/2011

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 06/22/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>was equipped with a self closing device on the door. This deficient practice could affect any of the 16 residents, as well as staff and visitors while in the 400 Unit.</p> <p>Findings include:</p> <p>Based on observation on 05/31/11 at 10:25 a.m. during a tour of the facility with Maintenance Supervisor, the Maintenance Shop, formally a resident room and over one hundred square feet in size, was full of combustible material including cardboard boxes, paper, plastic, and chemical supplies. The door to this room was not provided with a self closing device. This was acknowledged by the Maintenance Supervisor at the time of observation.</p> <p>3.1-19(b)</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN 47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0050 SS=C	<p>Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms. 19.7.1.2</p> <p>1. Based on record review and interview, the facility failed to ensure fire drills were held at varied times for 1 of 3 employee shifts during 3 of 4 quarters. This deficient practice could affect all residents in the facility.</p> <p>Findings include:</p> <p>Based on review of the facility's fire drills since May of 2010 in the Trilogy Plant Operations Manual on 05/31/11 at 9:30 a.m. with the Maintenance Supervisor present, three of four third shift fire drills were held 1:00 a.m. During an interview at the time of record review, the Maintenance Supervisor acknowledged the times of the third shift fire drills.</p> <p>3-1.19(b)</p>			K0050	<p>F 0050 There were no residents that suffered ill effects from the deficient practice. All residents have the potential to suffer ill affects from the deficient practice. A yearly schedule has been developed with pre-set times of drills to ensure that varying times are utilized in order to make drills more effective. ED/designee will monitor drills monthly for 6 months to make sure the varying times have been done. Results will be sent to QA x 6 months and any needed suggestions will be made.</p>		06/16/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>2. Based on record review and interview, the facility failed to ensure each documented fire drill included complete documentation of the transmission of a fire alarm signal to the monitoring company for 3 of 3 shifts during 4 of 4 quarters. LSC 19.7.1.2 requires fire drills in health care occupancies shall include the transmission of the fire alarm signal and simulation of emergency conditions. This deficient practice could affect all residents in the facility.</p> <p>Findings include:</p> <p>Based on review of the facility's fire drills since May of 2010 in the Trilogy Plant Operations Manual on 05/31/11 at 9:30 a.m. with the Maintenance Supervisor present, eight of twelve documented fire drill reports available during all three shifts did not include information the monitoring company received the transmission of the alarm. During an interview at the time of record review, the Maintenance Supervisor indicated the monitoring company was always</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0144 SS=F	<p>contacted before and after a fire drill was conducted during all shifts, but acknowledged some of the fire drill reports did not include this information.</p> <p>3-1.19(b)</p> <p>Generators are inspected weekly and exercised under load for 30 minutes per month in accordance with NFPA 99. 3.4.4.1.</p> <p>1. Based on record review and interview, the facility failed to provide complete documentation for the testing of 1 of 1 emergency generators providing power to the emergency lighting systems. LSC 7.9.2.3 and NFPA 99, Health Care Facilities, 3-4.4.1.1(a) requires that monthly testing of the generator set shall be in accordance with NFPA 110, the Standard for Emergency and Standby Power Systems. NFPA 110, 6-4.2 requires generator sets in Level 1 and 2 service shall be exercised under operating conditions or not less than 30 percent of the EPS (Emergency Power Supply) nameplate rating at least monthly, for a minimum of 30 minutes. NFPA 99, 3-5.4.2 requires a written record of</p>			K0144	<p>F 0144There were no residents that suffered ill effects from the deficient practice. All residents have the potential to suffer ill affects from the deficient practice. The maintenance supervisor has been in-serviced on the proper way to do the 3 phase generator test that includes the start and stop times and has developed a form to include the start and stop times of each test. There has been a remote shut off installed outside of the generator.</p>		06/16/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>inspection, performance, exercising period and repairs shall be regularly maintained and available for inspection by the authority having jurisdiction. This deficient practice could affect all residents, as well as staff and visitors in the facility.</p> <p>Findings include:</p> <p>Based on review of the facility's Generator Log on 05/31/11 at 9:50 a.m. with the Maintenance Supervisor present, the generator log form documented the generator was tested monthly under load since May of 2010, however, there was no documentation on the form that showed a start and stop time for each test, and only one phase of the three phase generator was documented during each test. During an interview at the time of record review, the Maintenance Supervisor confirmed the monthly generator log did not include documentation to show the start and stop times and the other two readings of the three phase generator.</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	3.1-19(b) 2. Based on observation and interview, the facility failed to ensure 1 of 1 emergency generators was equipped with a remote manual stop. LSC 7.9.2.3 requires emergency generators providing power to emergency lighting systems shall be installed, tested and maintained in accordance with NFPA 110, Standard for Emergency and Standby Power Systems. NFPA 110, 1999 edition, 3-5.5.6 requires Level II installations shall have a remote manual stop station of a type similar to a break-glass station located elsewhere on the premises where the prime mover is located outside the building. NFPA 37, Standard for the Installation and Use of Stationary Combustion Engines and Gas Turbines, 1998 Edition, at 8-2.2(c) requires engines of 100 horsepower or more have provision for shutting down the engine at the engine and from a remote location. This deficient practice could affect all occupants in the facility.						

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 06/22/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155723		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/31/2011	
NAME OF PROVIDER OR SUPPLIER RIVER POINTE HEALTH CAMPUS				STREET ADDRESS, CITY, STATE, ZIP CODE 3001 GALAXY DR EVANSVILLE, IN47715			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	Findings include: Based on observations on 05/31/11 between 10:25 a.m. and 11:45 a.m. during a tour of the facility with the Maintenance Supervisor and the Administrator, a remote shut off device was not found for the generator. Based on interview at 11:45 a.m., the Maintenance Supervisor acknowledged the generator was over 100 horsepower, and further indicated there was no remote shut off device for the generator. 3.1-19(b)						